

**I am having trouble polishing a travertine floor. I can get a good polish except for the fact that I have a lot of dull spots on the floor. Why is this and is there a way I can make the shine even across the surface?**

Travertine is a marble that has a lot of holes. These holes are filled at the factory with a colored Portland cement. When you polish the marble the fillers do not take a polish. This is why you get dull spots. The only way to eliminate the dull spots is to apply a coating on the surface of the marble. I would suggest a wax or a process known as recrystallization.

**TIP If you need to fill these holes try using a polyester or epoxy filler. These fillers will polish giving the travertine a uniform shine. Epoxy grout works great as a filler.**

Online URL:

<https://sr-manual.com/kb/article/i-am-having-trouble-polishing-a-travertine-floor-i-can-get-a-good-polish-except-for-the-fact-that-i-have-a-lot-of-dull-spots-on-the-floor-why-is-this-and-is-there-a-way-i-can-make-the-shine-even-across-the-surface-417.html>